

SUBJECT:

ENGINE OIL PUMP MEASUREMENT POSITION UPDATE

NO. TSB-89-11-007

DATE November, 1989

MODEL 1988 to 1989 Models

TSB Revision TSB 89-11-007

PURPOSE

In order to increase service accuracy, the oil pump gear tip measurement position has been moved. Shown in figures 1 and 2 the correct places to measure the clearance on both the drive gear and the driven gear. Please make the indicated changes to the service manuals listed below and write this TSB number in the TSB revision boxes on the affected pages. Clearance specifications have not changed. Please refer to the Service Manual for clearance specifications.

MANUALS AFFECTED

Manual	Applicable Page
1988 TRUCK Service Manual	9-49, 50
1989 TRUCK Service Manual	9-42
1988 VAN/WAGON Service Manual	9-64
1989 VAN/WAGON Service Manual	9-49
1989 GALANT Service Manual	9-72, 144
1989 MIRAGE Service Manual	9-133
1990 ECLIPSE Service Manual MSSP-002B-90 (1/2)	9-125




FIGURE 1




FIGURE 2

FILE UNDER: Group 11 Engine in the Dealer Service Information Binder

(714)

CIRCULATE TO:

016608

☐ GENERAL MANAGER

☐ PARTS MANAGER

☒ TECHNICIAN

☐ SERVICE ADVISOR

☒ SERVICE MANAGER

☐ WARRANTY PROCESSOR

☐ SALES MANAGER